

APPENDIX 2: SOLAR COLLECTOR PRODUCTION - NOTES AND SKETCHES

16 JUL 2012 /RADIONICA: SOLARNI KOLFUTOR!



18ECI DASNE PO MERI 1 SPOJITI SRAFOVIMA. NA UGLOVE NAMA ZATI DRWING.





ISECI BAMAPUE
CEVI I SPOJITI
T-VEZMAL.
NAMALICTI SVE
DODIRNE POVRĪINE
PASTOM ZA
LEMLJENJE.
PRE PASTE ODISTITI
SVE EN DELOVE
DD MASNOĆA!

BRENEROM LATERETATI
SPOJ PO SPOJ DOK PASTA NE
POTNE DA MENSA BOJU. JOS
MAZO GREJATI (5-10 S)
PA PRISLONITI 2-3 PUTA KALAJNU
ZICU (DEBLJU). ZICA ČE SE
STMA LAND TOPITI ALO JE
TEMPERATURA BOBORA.




PROBUTITI RUPICE.






LIMA DEBLINE DIS MM STROKE DIO 15 CM - 24 OPSIVANJE.




OVAJ KORAKIDE PRE PRETHODNOG :)
SPOJITI MREZU CEVI SA AL-KRILCIMA POMOĆU KOMADA
BANJARNE ZICE.





DVLAS PRITEBNUTI

TICK




PROVORITY IRALI SU KRICCA CVRSTA | STABILLA OFARBATI DONJI DED CEVME MIRETE SA KRILCIMA U CRINO.
OCISTITI RA ZREĐIVATEM PRE FARBANJA. FARBA SE ONA
STRANA NA KOJOJ JE VIDIJIVA CEZA USKA CEV!

POSTAVITI NA RADIN POURZINU DRUENI RAM, LIM ZA DINO (0,53) I TRANCE 2A OPTIVANJE (0,3 mm)



SAVITI RULOM PAZITI DA IVICE BUDU UREDNE




OPSIVANJE Ublova



USRAFFITI NA EVAILIH 15 CM+VASPOJEVIMA

SLOTITI KAMENU VUNU (5cm)
[AL FOLIJU (0.1 mm)

ZAHEFTATI FOUJU ZA DRVEND ROM,



CRMM STRANOM NA GORE. PAVEPITI DRVOFIKSOM ISECTENTE WANANCE.

KANK!

IFA I VENEA

1 STEERNI DED

V.Ansat &

NA VRAJU SE NA WOLDGER PRIEVECCUJE STAND PONDOU ANMINIUMSUNY L PROFILA. PRIEME SE POSTA VUJASU KA VNOTRA JNOOS STRAHI VOLGUTORA.

PRE POUTBYNIA STAWLA NA UNUTRASINU STRAW PAMA STAVUA (E SILIKON, NA KRAJU SE L PROFILI TAWBE ZAPUNDUJU SILIKONOM, POHERNO PO UGRAMMA.

